August 7, 2023

### Ceramics Lab - Building Materials Asbestos Data Summary

The California State Polytechnic University, Humboldt (Humboldt) Facilities Management (FM) Planning, Construction & Design (PDC) division collected bulk samples of suspect Asbestos Containing Material (ACM) at the Ceramics Lab (CERAM) building located at the following street address:

Ceramics Lab (Building 074) 1760 LK Wood Blvd, Arcata, CA 95521

Bulk sampling of suspect ACM was conducted throughout the exterior and interior of the CERAM building on July 12, 2023. This memorandum summarizes the laboratory analytical findings associated with this sampling and provides conclusions based on the lab data.

### **Project Site**

The CERAM building was originally built in 1950 and has footprint of approximately 7,000 square feet (SF). The CERAM exterior (foundation, walls, and roof) and interior (floors, walls, and ceilings) are herein defined as the project site.

The building is supported by concrete, steel, and wood structural components built on a concrete slab foundation. The exterior siding is a combination of wood shiplap, wood composite panel, and/or stucco. Interior floors consist of sealed and/or painted concrete slab. The roof consists of a bituminous rolled and composite shingle roofing systems overlaid on wooden roof deck. Roof penetrations throughout are sealed with mastic and/or caulking. Interior walls consist of exposed structural members, plywood paneling, cementitious paneling, or drywall. Interior ceilings consist of exposed framing (main ceramics lab), drywall hard lid (restrooms), wooden drop ceiling finished with acoustical ceiling tiles (administrative spaces), or cementitious panels (kiln area). Photographs of the project site are attached (Attachment A).

### **Survey Description**

A total 34 suspect ACM samples were collected throughout the project site, some samples consisting of multiple layers of unique materials. The samples collected at the project site are listed in Table 1 (page 2). The locations of bulk samples collected at the project site are depicted on Figure 1 (Attachment B). The distribution of asbestos materials at the project site is depicted on Figure 2 (Attachment B).

Sampling was conducted by a California Department of Industrial Relations, Division of Occupational Safety and Health (Cal/OSHA) Certified Asbestos Consultant (Scott Harris, CAC #11-4713). The ACM sampling was conducted in general conformance with the United States Environmental Protection Agency (USEPA) National Emission Standards for Hazardous Air Pollutants (NESHAP) regulations governing facility demolition.

### **Asbestos Findings**

Bulk samples collected from the project site were sent to SGS Forensic Laboratories located in Hayward, California. Samples were analyzed for asbestos content via Polarized Light Microscopy (PLM) using USEPA Method 600/R-93-Roof. The PLM data are summarized in Table 1.

Table 1 includes the sample location, material type, laboratory result, and applicable regulatory designations for each collected sample. Materials that were reported by the laboratory to be nondetect (i.e., no asbestos detected) are listed as "ND".

Samples reported to contain asbestos are identified in Table 1 by the asbestos content (percent asbestos) and highlighted using bold text. The approximate locations of the materials reported to contain asbestos are shown on Figure 2 (Attachment B). The PLM analytical reports are attached (Attachment C).

Table 1 – Asl	oestos Data Summ	ary				
Sample Number	Location	Material	Laboratory Result	USEPA Category	Cal/OSHA Work Class	Waste Designation
CERAM-1	Rm 101 NW Center	Concrete Slab (Grey)	ND	NA	NA	Not Asbestos Waste
CERAM-2	Rm 111 SE Center	Concrete Slab (Grey)	ND	NA	NA	Not Asbestos Waste
CERAM-3	SW Patio Kiln	TSI, Kiln Batt Insulation (White)	ND	NA	NA	Not Asbestos Waste
CERAM-4	Rm RR-1A S Window	Window Putty (White)	ND	NA	NA	Not Asbestos Waste
CERAM-5	Rm 108 N Kiln Heat Shield	TSI, Hood Batt Insulation (White)	ND	NA	NA	Not Asbestos Waste
CERAM-6	Rm 108 N Kiln Heat Shield	Cementitious Heat Shield (Grey)	ND	NA	NA	Not Asbestos Waste
CERAM-7	Rm 108 NE Wall	Drywall (White)	ND	NA	NA	Not Asbestos Waste
CERAM-8	Rm 108 NE Door	Drywall (White)	ND	NA	NA	Not Asbestos Waste
CERAM-9	Rm 108 S Center Ceiling	Cementitious Panel (Grey)	10% Chrysotile	Category II Nonfriable ACM	Class II	Nonhazardous Asbestos Waste
CERAM-10	Rm 108 S Wall	Hardie Backer Board (Tan)	ND	NA	NA	Not Asbestos Waste
CERAM-11	Rm 107 S Wall Kitchen Counter Backsplash	Fibrous Backsplash (Brown) + Mastic (Gold)	ND	NA	NA	Not Asbestos Waste
CERAM-12	Rm RR-1B SE Corner	Drywall + Joint Compound (White)	ND	NA	NA	Not Asbestos Waste
CERAM-13	Rm RR-1B SE Corner	4" Base (Black) + Mastic (Gold)	ND	NA	NA	Not Asbestos Waste
CERAM-14	RR Hallway E Wall	Drywall + Joint Compound (White)	ND	NA	NA	Not Asbestos Waste
CERAM-15	Rm 102 SW	Concrete Slab (Grey)	ND	NA	NA	Not Asbestos Waste
CERAM-16	Rm 102 Ceiling SW	12"x12" ACT (White/tan, nail- on)	ND	NA	NA	Not Asbestos Waste

Table 1 – As	bestos Data Summ	nary				
Sample Number	Location	Material	Laboratory Result	USEPA Category	Cal/OSHA Work Class	Waste Designation
CERAM-17	Rm E-1 E Wall	Drywall + Joint Compound (White)	ND	NA	NA	Not Asbestos Waste
CERAM-18	Rm 111 SE Corner	Drywall + Joint Compound (White)	<1% (Trace)	Presume ACM	Presume Class II Asbestos Work	Nonhazardous Asbestos Waste
CERAM-19	SW Patio Kiln	Fire Brick (Tan)	ND	NA	NA	Not Asbestos Waste
CERAM-20	Exterior Lower Flat Roof S Center Vent	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-21	Exterior Lower Flat Roof SE Skylight	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-22	Exterior Lower Flat Roof W Center S Kiln Vent	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-23	Exterior Lower Flat Roof E Center N Kiln Vent	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-24	Exterior NW Lower Flat Roof to Wall Flashing	Roof Mastic (Black) + Sealant (Clear)	ND	NA	NA	Not Asbestos Waste
CERAM-25	Exterior Lower Flat Roof N Exhaust Fan	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-26	Exterior Lower Flat Roof SW Skylight	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-27	Exterior NW Comp Roof- Roof to Wall Flashing	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-28	Exterior Upper Roof W Vent	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-29	Exterior Upper Roof NW HVAC Hood	Roof Mastic (Black)	ND	NA	NA	Not Asbestos Waste
CERAM-30	Exterior Lower Flat Roof N Center	Rolled Roofing (Red/Black)	ND	NA	NA	Not Asbestos Waste
CERAM-31	Exterior Lower Flat Roof SW	Rolled Roofing (Red/Black)	ND	NA	NA	Not Asbestos Waste
CERAM-32	Exterior Upper Roof W Center	Rolled Roofing (Red/Black)	ND	NA	NA	Not Asbestos Waste
CERAM-33	Exterior Comp Roof SW	Comp Shingle (Red/Black)	ND	NA	NA	Not Asbestos Waste

Table 1 – Ask	estos Data Summ	ary				
Sample Number	Location	Material	Laboratory Result	USEPA Category	Cal/OSHA Work Class	Waste Designation
CERAM-34	Exterior Comp Roof SE	Comp Shingle (Red/Black)	ND	NA	NA	Not Asbestos Waste

### Notes:

- ACM = Asbestos Containing Material (material reported to contain greater than 1% asbestos)
- NA = Not applicable
- ND = Nondetect (i.e., no asbestos fibers reported above the laboratory detection limit)
- RACM = Regulated Asbestos Containing Material (friable and greater than 1% asbestos)
- Individual materials comprising multi-layered samples are separated by a "+" sign

### **Conclusions for Asbestos**

As listed in Table 1, two (2) of the samples were reported to contain asbestos. These samples represent two (2) homogeneous areas of material distributed throughout the project site as shown on Figure 2 (Attachment B). All other sampled materials analyzed via PLM were reported to be ND. See attached PLM laboratory analytical reports (Attachment C).

Materials reported to contain greater than 1% asbestos are classified as either ACM or RACM depending on each material's physical characteristics. Material containing greater than 0.1% asbestos is designated by Cal/OSHA as Asbestos Containing Construction Material (ACCM). Asbestos materials that may be disturbed by the project shall be removed by a licensed abatement contractor prior to other site work.

Nonfriable ACM is classified as nonhazardous asbestos waste, so long as the material is not rendered friable during removal. Nonfriable ACM shall be reclassified as Regulated ACM (RACM), if removed using mechanical means, or otherwise rendered friable. Asbestos is not federally regulated as a hazardous waste under the Resource Conservation and Recovery Act (RCRA). Friable material containing greater than 1% asbestos (e.g., RACM) is regulated as a hazardous waste in California, thus is classified as a non-RCRA California hazardous waste. If other constituents of concern are presumed to be present onsite, then the demolition waste stream must be representatively sampled to determine the concentration of such constituents in that waste. Transportation and disposal requirements shall be determined based on the waste characterization data.

Any suspect ACM not identified in this memorandum that is discovered during site work should be presumed to contain asbestos until sampled and proven otherwise. If suspect ACM is identified at the project site for which there is no existing data, then work in that area shall stop, the material wetted, and access to the area restricted until the suspect ACM can be appropriately sampled and characterized. Please contact FM PDC with any questions regarding the information contained in this memorandum.

Thank you,

Facilities Management - Planning, Design & Construction

Scott Harris, CAC, CDPH

(707) 826-5904 scott.harris@humboldt.edu

### Attachments:

- Attachment A Site Photographs
- Attachment B Sample Location and Asbestos Distribution Figures
- Attachment C Laboratory Data



Photograph 1 – CERAM Exterior – East façade



Photograph 2 – CERAM Interior – Main classroom looking east



Photograph 3 – CERAM Exterior – Exterior kiln enclosure



Photograph 4 – CERAM Exterior – South façade and roof



Photograph 5 – CERAM Interior – Cementitious panel (typical) reported to be ACM



Photograph 6 – CERAM Interior – Room 108 Cementitious panel (ACM) at ceiling



Photograph 7 – CERAM Interior – Cementitious panel (ACM) at walls and ceiling (typical)



Photograph 8 – CERAM Interior – Drywall and joint compound walls and ceiling (typical) reported to contain asbestos




Photograph 9 – CERAM Interior – Drywall and joint compound walls and ceiling (typical) reported to contain asbestos



Photograph 10 – CERAM Interior – Drywall and joint compound wall (typical) reported to contain asbestos

# Attachment B Figure 1 - Sample Location Map

Ceramics Lab (074)




### Notes:

- All locations and measurements approximate
- Not to scale
- CERAM # = Sample Location
- -Out lined box + Bold lettering = Material reported to contain asbestos
- = = = = = = Drywall wall associated with joint compound on walls reported to contain asbestos
- -///= Drywall wall associated with joint compound on ceiling reported to contain asbestos
- Cementitious paneling on walls reported to contain asbestos
- = Cementitious paneling on ceiling reported to contain asbestos



## Attachment B Figure 2 - Distribution & Quantity Detail Ceramics Lab (074)



#### Notes:

- All locations and measurements approximate
- Not to scale
- CERAM # = Sample Location
- -Out lined box + Bold lettering = Material reported to contain asbestos
- ■ ■ ■ Drywall wall associated with joint compound on walls reported to contain asbestos
- -////= Drywall wall associated with joint compound on ceiling reported to contain asbestos
- Cementitious paneling on walls reported to contain asbestos
- Ecementitious paneling on ceiling reported to contain asbestos
- Approximately 4500 SF of drywall associated with joint compound reported to contain asbestos
- Approximately 900 SF of cementitious panel reported to contain asbestos





## **Bulk Asbestos Analysis**

(EPA Method 40CFR, Part 763, Appendix E to Subpart E and EPA 600/R-93-116, Visual Area Estimation) NVLAP Lab Code: 101459-0

Cal-Poly Humboldt (State University) **Client ID:** 2087 Scott Harris B349631 **Report Number:** 1 Harpst Street **Date Received:** 07/17/23 Plan Operations **Date Analyzed:** 07/19/23 Arcata, CA 95521 **Date Printed:** 07/20/23 07/19/23 First Reported: Job ID/Site: PO# 1127193/XPL298; FM PDC / PLY 106 - Ceramics Lab (075) - 1770 LK Wood Blvd SGSFL Job ID: 2087-1 **Total Samples Submitted: 34 Date(s) Collected: Total Samples Analyzed:** Percent in Asbestos Percent in Asbestos Percent in Asbestos Sample ID Lab Number Layer Type Layer Type Type Layer **CERAM-1** 12677678 Layer: Grey Cementitious Material ND Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (Trace) CERAM-2 12677679 Layer: Grey Cementitious Material ND Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (Trace) **CERAM-3** 12677680 Layer: White Fibrous Material ND Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (Trace) Fibrous Glass (99 %) **CERAM-4** 12677681 ND Layer: Off-White Non-Fibrous Material Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (Trace) 12677682 **CERAM-5** Layer: White Fibrous Material ND Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (Trace) Fibrous Glass (99 %) **CERAM-6** 12677683 ND Layer: Grey Cementitious Material Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (Trace) CERAM-7 12677684 ND Layer: White Drywall Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (20 %) **CERAM-8** 12677685 Layer: White Drywall ND Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (20 %)

Report Number: B349631
Client Name: Cal-Poly Humboldt (State University)
Date Printed: 07/20/23

Chem Name: Cal-Poly Humboldt (State	Oniversity)				Date Frinteu:	07/20/2	43
Sample ID	Lab Numbe	Asbestos er Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
CERAM-9 Layer: Grey Semi-Fibrous Cementitiou	12677686 s Materia	Chrysotile	10 %				
Total Composite Values of Fibrous Cor Cellulose (Trace)	mponents:	Asbestos (10%)					
CERAM-10 Layer: Tan Semi-Fibrous Material	12677687		ND				
Total Composite Values of Fibrous Cor Cellulose (15 %) Fibrous Glass (T	•	Asbestos (ND)					
CERAM-11  Layer: Brown Semi-Fibrous Material  Layer: Tan Mastic	12677688		ND ND				
Total Composite Values of Fibrous Con Cellulose (25 %)	nponents:	Asbestos (ND)					
CERAM-12 Layer: White Drywall Layer: Off-White Joint Compound Layer: Paint	12677689		ND ND ND				
Total Composite Values of Fibrous Con Cellulose (20 %) Fibrous Glass (10	-	Asbestos (ND)					
CERAM-13  Layer: Black Non-Fibrous Material  Layer: Yellow Mastic	12677690		ND ND				
Total Composite Values of Fibrous Cor Cellulose (Trace)	nponents:	Asbestos (ND)					
CERAM-14  Layer: White Drywall  Layer: Off-White Joint Compound  Layer: Paint	12677691		ND ND ND				
Total Composite Values of Fibrous Con Cellulose (20 %) Fibrous Glass (10	•	Asbestos (ND)					
CERAM-15 Layer: Grey Cementitious Material	12677692		ND				
Total Composite Values of Fibrous Cor Cellulose (Trace)	mponents:	Asbestos (ND)					
CERAM-16 Layer: Tan Fibrous Material Layer: Paint	12677693		ND ND				
Total Composite Values of Fibrous Cor Cellulose (95 %)	nponents:	Asbestos (ND)					

**Report Number:** B349631 **Date Printed:** 07/20/23

Client Name: Cal-Poly Humboldt (State University)

Client Name: Cal-Poly	Humboldt (State U	niversity)				Date Printed:	: 07/20/	23
Sample ID		Lab Number	Asbestos r Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
CERAM-17 Layer: White Drywall Layer: Off-White Join Layer: Drywall Tape Layer: Off-White Join Layer: Paint	t Compound	12677694		ND ND ND ND				
Total Composite Valu	es of Fibrous Comp Fibrous Glass (10	•	Asbestos (ND)	T(D)				
CERAM-18 Layer: White Drywall Layer: Off-White Join Layer: Drywall Tape Layer: Off-White Join Layer: Paint	t Compound	12677695	Chrysotile	ND Trace ND ND ND				
Total Composite Valu Cellulose (20 %)	es of Fibrous Comp Fibrous Glass (10	•	Asbestos (Trace)	)				
CERAM-19 Layer: Off-White Non	-Fibrous Material	12677696		ND				
Total Composite Valu Cellulose (Trace)	es of Fibrous Com	ponents:	Asbestos (ND)					
CERAM-20 Layer: Black Mastic		12677697		ND				
Total Composite Valu Cellulose (5 %) F	es of Fibrous Comj ibrous Glass (2 %)	•	Asbestos (ND)					
CERAM-21 Layer: Black Mastic		12677698		ND				
Total Composite Valu Cellulose (10 %)	es of Fibrous Com <sub>j</sub> Fibrous Glass (Tra	•	Asbestos (ND)					
CERAM-22 Layer: Black Mastic		12677699		ND				
Total Composite Valu Cellulose (10 %)	es of Fibrous Com <sub>j</sub> Fibrous Glass (Tra	•	Asbestos (ND)					
CERAM-23 Layer: Black Mastic Layer: Black Semi-Fil	orous Material	12677700		ND ND				
Total Composite Valu Cellulose (10 %)	es of Fibrous Comp Fibrous Glass (Tra	•	Asbestos (ND)					
CERAM-24 Layer: Black Mastic Layer: Black Semi-Fib	orous Material	12677701		ND ND				
Total Composite Valu Cellulose (Trace)	es of Fibrous Comp Fibrous Glass (Tra	•	Asbestos (ND)					

Report Number: B349631

Date Printed: 07/20/23

Client Name: Cal-Poly Humboldt (State University)

Client Name: Cal-Pol	y Humboldt (State University)				Date Printed:	: 07/20/2	23
Sample ID	Lab Numb	Asbestos er Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
CERAM-25 Layer: Black Mastic	12677702		ND				
Total Composite Va Cellulose (10 %)	lues of Fibrous Components: Fibrous Glass (Trace)	Asbestos (ND)					
CERAM-26 Layer: Black Mastic	12677703		ND				
Total Composite Va Cellulose (10 %)	lues of Fibrous Components: Fibrous Glass (Trace)	Asbestos (ND)					
CERAM-27 Layer: Black Mastic	12677704		ND				
Total Composite Va Cellulose (10 %)	lues of Fibrous Components: Fibrous Glass (Trace)	Asbestos (ND)					
CERAM-28 Layer: Black Mastic	12677705		ND				
Total Composite Va Cellulose (10 %)	lues of Fibrous Components: Fibrous Glass (Trace)	Asbestos (ND)					
CERAM-29 Layer: Black Mastic	12677706		ND				
Total Composite Va Cellulose (10 %)	lues of Fibrous Components: Fibrous Glass (Trace)	Asbestos (ND)					
CERAM-30 Layer: Red Roof Shi Layer: Black Roof S	_		ND ND				
Total Composite Va Cellulose (55 %)	lues of Fibrous Components: Fibrous Glass (10 %)	Asbestos (ND)					
CERAM-31 Layer: Red Roof Shi Layer: Black Roof S	0		ND ND				
Total Composite Va Cellulose (55 %)	lues of Fibrous Components: Fibrous Glass (10 %)	Asbestos (ND)					
CERAM-32 Layer: Red Roof Shi Layer: Black Roof S	2		ND ND				
Total Composite Va Cellulose (55 %)	lues of Fibrous Components: Fibrous Glass (10 %)	Asbestos (ND)					
CERAM-33 Layer: Red Roof Shi Layer: Black Roof S	•		ND ND				
Total Composite Va Cellulose (55 %)	lues of Fibrous Components: Fibrous Glass (10 %)	Asbestos (ND)					

**Report Number:** B349631

Client Name: Cal-Poly Humboldt (State University) **Date Printed:** 07/20/23

Percent in Asbestos Percent in Asbestos Percent in Asbestos Sample ID Lab Number Type Layer Type Layer Type Layer 12677970 CERAM-34 Layer: Red Roof Shingle ND Layer: Black Roof Shingle ND

Total Composite Values of Fibrous Components: Asbestos (ND)

Cellulose (55 %) Fibrous Glass (10 %)

Note: Job ID, Site updated

Maria Cosper, Laboratory Supervisor, Hayward Laboratory

Maria E. Casper

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by SGS Forensic Laboratories (SGSFL) at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by SGSFL to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by SGSFL. The client is solely responsible for the use and interpretation of test results and reports requested from SGSFL. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. SGSFL is not able to assess the degree of hazard resulting from materials analyzed. SGS Forensic Laboratories reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.



### Analysis Request Form (COC)

Client Name & Address:		Client No.: 2087	PO / Job#: F	M PDC /	PLY106	Date	07/13/2	2023	
Cal Poly Humboldt			Turn Around T	ime: Same	Day / 1Day				
Facilities Management 1 Harpst Street, Arcata		.8200	PCM: N		- Land	d balance	h	otometer	
Thaipst Oticet, Alcata	, CA 3332	1-0299	■ PLM: ■ Standard / □ Point Count 400 - 1000 / □ CARB 435						
Contact: Scott Harris	Phon	e: (707) 826-5904	☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield						
E-mail: ssh11@humboldt	edu, jrb20	@humboldt.edu	TEM Water					%	
Site Name: Ceramics Lab	□ IAQ Particle □ Particle Ide				PLM Opc	ques/Soot			
Site Location: 1760 LK Wo	od Blvd, Ar	cata, CA 95521	☐ Metals Ana		x:		thod:		
Comments: CF: 607022 HM7	05 D30037	PLY106. Please send invo	oices to above ema	233		Silica		w/Gravimetry	
	- T				FOR AIR SA			Sample	
Sample ID	Date / Time	Sample Location /	Description	Туре	Time On/Off	Avg LPM	Total Time	Area / Air Volume	
See Attachment A	07/12/23	See Attachment A		P	NA	- NA	NA	NA	
				A					
				C					
				P					
				P					
				A			ĦŦ		
			_	IA IA					
				P					
				A				1	
				IA I					
				A P					
-				A					
				A					
Sandad Burgar	Data /Times	As above Shipped Via:	∏ Fed Ex ☑ UPS	C	ail <b>T</b> Courie	or Fibr	op Off Ti	Othor	
Sampled By: SH  Relinquished By: Scott Harr	Date/Time:	As above Shipped Via:	LITEGIEX MUPS	11 US M	Relinquished		op Oil I.I	Ollier.	
Date / Time: 07/13/2023 1	745 1805	177			Date / Time:				
Received By:	085	Received By:			Received By:				
Date / Time: JUL 1 77 Condition Acceptate  TYes	2023 103	Date / Time: Condition Acceptable	e? D'Yes DIN	lo.	Date / Time: Condition Ac		ПУ	□ No	

Project: PLY106	Site: Ceramics Lab (74)	Sample Date: 07/12/2023		
	Bulk Sample Matri	x		
Sample Number	Location	Material Description		
CERAM-1	Rm 101 NW Center	Concrete Slab (Grey)		
CERAM-2	Rm 111 SE Center	Concrete Slab (Grey)		
CERAM-3	SW Patio Kiln	TSI, Kiln Batt Insulation (White)		
CERAM-4	Rm RR-1A S Window	Window Putty (White)		
CERAM-5	Rm 108 N Kiln Heat Shield	TSI, Hood Batt Insulation (White)		
CERAM-6	Rm 108 N Kiln Heat Shield	Cementitious Heat Shield (Grey)		
CERAM-7	Rm 108 NE Wall	Drywall (White)		
CERAM-8	Rm 108 NE Door	Drywall (White)		
CERAM-9	Rm 108 S Center Ceiling	Cementitious Panel (Grey)		
CERAM-10	Rm 108 S Wall	Hardie Backer Board (Tan)		
CERAM-11	Rm 107 S Wall Kitchen Counter Backsplash	Fibrous Backsplash (Brown) + Mastic (Gold)		
CERAM-12	Rm RR-1B SE Corner	Drywall + Joint Compound (White)		
CERAM-13	Rm RR-1B SE Corner	4" Base (Black) + Mastic (Gold)		
CERAM-14	RR Hallway E Wall	Drywall + Joint Compound (White)		
CERAM-15	Rm 102 SW	Concrete Slab (Grey)		
CERAM-16	Rm 102 Ceiling SW	12"x12" ACT (White/tan, nail-on)		
CERAM-17	Rm E-1 E Wall	Drywall + Joint Compound (White)		
CERAM-18	Rm 111 SE Corner	Drywall + Joint Compound (White)		
CERAM-19	SW Patio Kiln	Fire Brick (Tan)		
CERAM-20	Ext Lower Flat Roof S Center Vent	Roof Mastic (Black)		
CERAM-21	Ext Lower Flat Roof SE Skylight	Roof Mastic (Black)		
CERAM-22	Ext Lower Flat Roof W Center S Kiln Vent	Roof Mastic (Black)		
CERAM-23	Ext Lower Flat Roof E Center N Kiln Vent	Roof Mastic (Black)		
CERAM-24	Ext NW Lower Flat Roof to Wall Flashing	Roof Mastic (Black) + Sealant (Clear)		
CERAM-25	Ext Lower Flat Roof N Exhaust Fan	Roof Mastic (Black)		
CERAM-26	Ext Lower Flat Roof SW Skylight	Roof Mastic (Black)		
CERAM-27	Ext NW Comp Roof-Roof to Wall Flashing	Roof Mastic (Black)		
CERAM-28	Ext Upper Roof W Vent	Roof Mastic (Black)		
CERAM-29	Ext Upper Roof NW HVAC Hood	Roof Mastic (Black)		
CERAM-30	Ext Lower Flat Roof N Center	Rolled Roofing (Red/Black)		
CERAM-31	Ext Lower Flat Roof SW	Rolled Roofing (Red/Black)		



Project: PLY106	Site: Ceramics Lab (74)	Sample Date: 07/12/2023			
	Bulk Samp	le Matrix			
Sample Number	Location	Material Description			
CERAM-32	Ext Upper Roof W Center	Rolled Roofing (Red/Black)			
CERAM-33	Ext Comp Roof SW	Comp Shingle (Red/Black)			
CERAM-34	Ext Comp Roof SE	Comp Shingle (Red/Black)			
Notes:					
Please provide a resu	ılt for each unique material comprising mu	Itilayered samples.			
ACT	Acoustical Ceiling Tile				
CTR	Center				
JC	Joint Compound				
N, S, E, W, NW, etc.	Azimuth directions				
TSI	Thermal System Insulation				
√FT	Vinyl floor tile				
VSF	Vinyl sheet flooring				